


All dimensions in millimeters



The Control box cover (6 pcs phillips screws) must be removed when mounting the box with fastening hex screws (2 pcs M4 x 20)



Attention! The Control box should be mounted on a metal surface for heat conduction.