


Control Box for Clean Line conveyor

All Dimensions in millimeters



The Control box cover (6 pcs phillips screws) must be removed when mounting the box (2 pcs M4 x 20 mm hex screws)



Attention! The Control box must be mounted on a metal surface for heat conduction.

Address:

Conveyor 22 AB
Grånumsvägen 390
293 93 Olofström, Sweden

Phone:

+46 (0)454-432 21

E-mail:

kontakt@conveyor22.se

Internet:

www.conveyor22.se

VAT no:

556881-0393
SE556881039301