



Dimensions and Hole Pattern Drawing Control Box for Clean Line conveyor




5.70"

Dimensions in millimeters




Dimensions in inches



223

145



210

115

The Control box cover (6 pcs phillips screws) must be removed when mounting the box (2 pcs M4 x 0,8" hex screws)



Attention! The Control box must be mounted on a metal surface for heat conduction.

